Attachment F

EXISTING STOREFRONT SYSTEM

Existing storefront system - Dark Bronze Anodized Finish



Ayars & Ayars INCORPORATED

ARCHI + ETC.LLC
ARCHITECTURE ETCETERA

NOTE: Image shows design intent only. Reference the construction documents for actual building construction

PROPOSED WINDOW REPLACEMENT WITH GARAGE DOORS

All material to match existing storefront system

This window was used as example due to poor lighting of window under canopy. See plan for actual location of windows to be replaced.



Ayars & Ayars INCORPORATED

ARCHI + ETC.LLC
ARCHITECTURE ETCETERA

NOTE: Image shows design intent only. Reference the construction documents for actual building construction